



PO Box 457
Turramurra NSW 2074

ABN: 69 041 751 671

PH: 0437 251 358
Email: philclifton@pclifton.com

21 October 2022

Mr John Sabbouh
Richard Crookes Constructions
Level 3, 4 Broadcast Way
Artarmon NSW 2064

**RE: RESULTS OF AIRBORNE ASBESTOS FIBRE MONITORING
CTC BUILDING AT THE ST JOHN OF GOD RICHMOND HOSPITAL
177 GROSE VALE ROAD, NORTH RICHMOND NSW**

Dear Sir,

We refer to your request to undertake monitoring for airborne asbestos fibres on Wednesday 19 October 2022 during and following the removal of asbestos backed sheet vinyl floor coverings from within the northern St Pauls area in the CTC Building located within the Richard Crookes Constructions site at the St John of God Richmond Hospital, 177 Grose Vale Road, North Richmond NSW.

This monitoring was carried out in accordance the requirements of the Safe Work Australia How to Safely Remove Asbestos Code of Practice, Section 3.11 and the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres' 2nd edition [NOHSC 3003:2005].

The results of the monitoring are as follows:

Sample No.	Location	Time On	Time Off	Fibre Count fibres/fields	Airborne Fibre Concentration (fibres/ml)
PCA 7420 - 2022/NR1/71	At decontamination unit in centre corridor	07:00	14:00	0.0/100	<0.01
PCA 7420 - 2022/NR2/72	At neg air unit on north end outside building	07:02	14:02	0.0/100	<0.01
PCA 7420 - 2022/NR3/73	Clearance in work area, north	12:05	14:05	0.0/100	<0.01
PCA 7420 - 2022/NR4/74	Clearance in work area, south	12:06	14:06	0.0/100	<0.01

The above results are below the lowest detectable level for the estimation of airborne asbestos fibres using the membrane filter method and below the NOHSC recommended exposure level for airborne asbestos fibres (8 hour TWA) of 0.1 fibres/ml. Green shading indicates results below limit of detection.



Page 2 of 2
21 October 2022

This result indicates that there was no measurable human health risk from airborne asbestos fibres in these areas during the monitoring period.

The NATA endorsed laboratory report is attached.

If you require any further information, please contact me on 0437 251 358.

Yours faithfully

P. CLIFTON & ASSOCIATES PTY LTD

Philip Clifton
Principal
BOHS IP402 Certified
SafeWork NSW Licenced Asbestos Assessor: LAA000119

Attachment: Laboratory Report



LABORATORY REPORT

CERTIFICATE OF AIR MONITORING

Date: 21 October 2022

ESP Job Number: J47248

Customer: P. Clifton & Associates Pty Ltd

Address: PO Box 457, Turramurra, NSW

Attention: Phil Clifton

Sampled From: As received (Your ref: 7420 - 2022, North Richmond)

Sampled By: As received

Date Received: 21 October 2022

Date Analysed: 21 October 2022

Test Method: Filters examined in accordance with Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] using ESP in-house Method No. 1.

ESP Lab No.	Customer Reference	Result (fibres/field)
81448	NR1/71 - CTC - decon (19/10/22)	Nil / 100
81449	NR2/72 - CTC - North	Nil / 100
81450	NR3/73 - CTC clearance South	Nil / 100
81451	NR4/74 - CTC - clearance North	Nil / 100

The results contained in this report relate only to the sample(s) submitted for testing. ESP Environmental & Safety Professionals accepts no responsibility for the representivity of the sample(s) submitted.

Approved Fibre Counter(s): Eric Salter
Approved Signatory: Eric Salter

